




000000000 000000000 **CAUTION:** TO REDUCE RISK OF FIRE OR PERSONAL INJURY, USE ONLY BATTERY LISTED IN USER BOOK ATTENTION: AFIN DE RÉDUIRE LES RISQUES D'INCENDIE ET DE BLESSURE, UTILISER SEULEMENT LA PILE DE L'UTILISATEUR. MODEL NO.:28111EE1-MADE IN CHINA THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL 28111EE1-A DYWWHY S/NO:YXXXXXXX INTERFERENCE AND (2) THIS DEVICE MUST ACCEPT ANY Thomson Inc. INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION. MODEL NO.:28111EE1-A IC: 3675A-28111A US:G9HW400B28111-A MADE IN CHINA FABRIQUE EN CHINE FCC ID:G9H2-8111A MODEL NO.:28111EE1-A IC: 3675A-28111A For canada only 2

28111EE-1A LABEL DRAWING DATE: JUL 05.06









THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION. IC: 3675A-28111A

MADE IN CHINA FABRIQUE EN CHINE US:G9HW400B28111-A FCC ID:G9H2-8111A



28111EE-2A LABEL DRAWING **DATE: JUL 05.06** 



INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT

US:G9HW400B28111-A

FCC ID:G9H2-8111A

REN:0.0B


MAY CAUSE UNDESIRED OPERATION.


IC: 3675A-28111A


FABRIQUE EN CHINE

MADE IN CHINA


28111EE-3A LABEL DRAWING DATE:JUL 05.06









MODEL No.:TC28112EEX-A








TC28112EEX-A DYWWDO

LABEL DRAWING FOR 28112EEX-A(USA & CAN)

Remark: EEX=EE1/EE2/EE3
Revised Date: 06 Jul.06



LABEL DRAWING FOR 28110EE1-A(USA & CAN)
Revised Date: 06 Jul.06

