

07 January 2008

American TCB
6731 Whittier Avenue
McLean VA 22101

RE: DataCard
Response to 12-17-2007 Comments

FCC ID: GDI-SCRDTX

In response to your comments on the above submittal from 12-17-2007.

1. ATCB Comments: Please clarify the label exhibit. It appears that the label that says "Contains FCC ID:" is actually going to be placed on the module itself. If so, please modify. The label on the module should NOT say "Contains FCC ID:" it should just show the FCC (and Canadian) ID. If this label is intended to go on the host, please provide a drawing of the label that will appear on the module itself.

RESPONSE: Revised exhibit uploaded.

2. ATCB Comments: It appears that the label exhibit shows the label being attached to the antenna that is used with the device. The label should appear on the radio module itself. Not the antenna "board"

RESPONSE: Revised exhibit uploaded.

3. ATCB Comments: The FCC ID noted in the operational description in section 3.6.3 is incorrect. Please correct.

RESPONSE: Revised exhibit uploaded.

4. ATCB Comments: Please incorporate the 15.21 "No Modification" statement in the user manual.

RESPONSE: Revised manual has been uploaded.

Please let us know if anything further is required.

Susan L Rupp

Susan L Rupp, Technical Writer
TÜV America Inc
Tel: 651 638 4585 / Fax: 651 638 0298
srupp@tuvam.com