



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 20, 2007

RE: Pison Teklogix Inc.

FCC ID: GM37525BTB

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide appropriate RF exposure information for documentation of the co-location configurations as requested in this application. Note that it is my understanding that these results already have been reviewed for the associated co-located transmitter(s) application and there are comments regarding the positioning of the units for SAR. Once these comments have been resolved, please provide the latest RF exposure information, as well as copies of the RF exposure related questions/response for documentation of this application as appropriate.
- 2) Since this is a LMA in a particular host which differs from previous hosts under this FCC ID, please provide associated internal/external photographs of the new host(s) to sufficiently document this application.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.