


# Appendix C. Set up Photograph

# Spurious Radiation 7527C




#### FRONT VIEW

REAR VIEW

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No.:C1 of C3Report Issued Date:May 14, 2007Report Version:Rev. 03



### 7527S




FRONT VIEW

**REAR VIEW** 

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No.:C2 of C3Report Issued Date:May 14, 2007Report Version:Rev. 03



## 7527C with Pistol Grips



FRONT VIEW

REAR VIEW

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No.:C3 of C3Report Issued Date:May 14, 2007Report Version:Rev. 03