T 905 813 9900 F 905 812 6300

INGENUITYWORKING.COM PSION.COM



Date: October 18, 2013

To Whom It May Concern

Subject:

Software Security Measure

Applicant:

Psion Inc.

FCC ID:

GM38516

Dear Sir/Madam,

All transmitter settings are internal to the software; user has no access to modify non-volatile memory location where the transmitter settings are stored.

Regards,

(Sada Dharwarkar)

Group Leader, Radio Approvals