

Product Information (con't)

FCC Compliance - This device does not comply with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause unwanted operation.

This equipment is being tested to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following safety measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Consult the dealer or an experienced radio modem technician for help.

This device is required to comply with FCC RF exposure requirements for mobile transmitting devices. A separation distance of 20 cm (8 inches) or more must be maintained between the antenna and all persons during device operations to satisfy RF exposure compliance.

Ricochet Internet Settings

- Primary DNS: 168.253.48.19
- Secondary DNS: 198.6.1.1
- Dial String: 222
- POP Host: pop.ricochet.net
- SMTP Host: smtp.ricochet.net
- News/NNTP Host: news.ricochet.net

Recommended Modem Settings

- RS-232 Serial Port Speed: 115200 baud
- PC Card High Speed Serial Port: 115200 baud
- Macintosh Serial Port: 230400 baud
- Flow Control: Hardware (CTS & RTS [DTR])
- USB Port: Not Supported at this time.