TRW Automotive U.S. LLCd.b.a TRW Automotive Electronics24175 Research DriveFarmington Hills, MI 48335Tel:248.478.7210Fax:248.478.7241

RE: Certification for TRW TPM '05 Highline Receiver with Initiator

Highline Receiver Model #: 95800-26000 Initiator Model #: 95800-3E300 FCC ID: GQ4-39R Canada IC: 1470A-11R

BLOCK DIAGRAM




Figure 3a. TPM Highline Receiver Block Diagram

TRW Automotive U.S. LLCd.b.a TRW Automotive Electronics24175 Research DriveFarmington Hills, MI 48335Tel:248.478.7210Fax:248.478.7241

RE: Certification for TRW TPM '05 Highline Receiver with Initiator Highline Receiver Model #: 95800-26000 Initiator Model #: 95800-3E300

FCC ID: GQ4-39R Canada IC: 1470A-11R




Figure 3b. TPM Highline Receiver Block Diagram