

August 9, 2013

TEE
24175 Research Dr.
Farmington Hills, MI 48335-2642
Tel 248.478.7210
Fax 248.699.4241

RE: Certification for Honda 315MHz ASK AA FACI HL/BL Sensor

FCC ID: GQ4-68T
Canada IC: 1470A-49T
Model #: 225260-105, -106

User's Manual and Compliance Statement

The DS IGNM is individually sold by the distributing supplier and as such it will require each module sold to be accompanied with the FCC Statement Part 15.

The compliance statement for the DS IGNM will read:

FCC ID: GQ4-68T

IC: 1470A-49T

This device complies with Part 15 of the FCC Rules and with RSS-210 of Industry Canada. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

Le present appareil est conforme aux CNR d'Industrie Canada applicable aux appareils radio exempts de licence. L'exploitation est autorisee aux deux conditions suivantes:

1. L'appareil ne doit pas produire de brouillage.
2. L'utilisateur de l'appareil doit accepter tout brouillage radioelectrique subi, meme si le brouillage est susceptible d'en compromettre le fonctionnement.

WARNING: Changes or modifications not expressly approved by TRW Automotive U.S. LLC could void the user's authority to operate the equipment.

The term "IC:" before the radio certification number only signifies that Industry Canada technical specifications were met.