

January 24, 2014

TEE  
24175 Research Dr.  
Farmington Hills, MI 48335-2642  
Tel 248.478.7210  
Fax 248.699.4241

RE: Certification for AFM Honda/HKMC 315MHz ASK HL/BL TPM Sensor  
Model #: 218898-105 (High Line Short Valve Stem)  
218898-106 (High Line Long Valve Stem)  
218898-107 (Base Line Short Valve Stem)  
FCC ID: GQ4-69T  
Canada IC: 1470A-50T

## **USER'S MANUAL & COMPLIANCE STATEMENT**

The TPM Transmitter is sold as part of a vehicle by the retail automobile dealers and as such has no separate manual. This exhibit is provided electronically to the vehicle manufacturer after submission.

The compliance statement for the TPM Transmitter (FCC ID: GQ4-69T) will be integrated by the OEM into the vehicle owner's manual. It will read:

This device complies with Part 15 of the FCC Rules and with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions:

1. This device may not cause harmful interference.
2. This device must accept any interference received, including interference that may cause undesired operation.

Le present appareil est conforme aux CNR d'Industrie Canada applicable aux appareils radio exempts de licence. L'exploitation est autorisee aux deux conditions suivantes:

1. L'appareil ne doit pas produire de brouillage.
2. L'utilisateur de l'appareil doit accepter tout brouillage radioelectrique subi, meme si le brouillage est susceptible d'en compromettre le fonctionnement.

**WARNING:** Changes or modifications not expressly approved by TRW Automotive U.S. LLC could void the user's authority to operate the equipment.