

Active & Passive Safety Technology Business Unit

Certification for Toyota MY18 305B FSK 315 MHz TPM SensorFCC ID:GQ4-72TCanada IC:1470A-53TModel #:335098-101, 335098-102

## **USER'S MANUAL & COMPLIANCE STATEMENT**

The TPM Sensor is sold only as part of a vehicle by the retail automobile dealers and as such has no separate manual. This exhibit is provided electronically to the vehicle manufacturer after submission.

The compliance statement for the TPM Sensor (FCC ID: GQ4-72T) will be integrated by the OEM into the vehicle owner's manual. It will read:

This device complies with Part 15 of the FCC Rules and with RSS Standards of Industry Canada. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

Le present appareil est conforme aux CNR d'Industrie Canada applicable aux appareils radio exempts de licence. L'exploitation est autorisee aux deux conditions suivantes:

- 1. L'appareil ne doit pas produire de brouillage.
- 2. L'utilisateur de l'appareil doit accepter tout brouillage radioelectrique subi, meme si le brouillage est susceptible d'en compromettre le fonctionnement.

WARNING: Changes or modifications not expressly approved by TRW Automotive U.S. LLC could void the user's authority to operate the equipment.

The term "IC:" before the radio certification number only signifies that Industry Canada technical specifications were met.