



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

February 23, 2005

RE: Visonic Ltd.

FCC ID: GSAMCTIIR252

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Simply explaining to the user to keep SW 2, 3, and 6 off in the manual is not sufficient for the FCC. Please refer to 15.15 of the rules. Basically there must be some way that the user can not enable these features. Either the switches for these numbers do not exist, the connection to these switches do not exist, firmware/software is set such that the switches do not function, etc. Please explain how the device will be compliant to 15.15 given these features or alternatively provide a response to the previous questions 2, 3, 4, and 5 as appropriate that shows compliance to 15.231.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.