



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 18, 2006

RE: Visonic Ltd.

FCC ID: GSAPWRMAXPRO

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please justify the use of the FCC DoC Logo. It is uncertain why this is used.
- 2) What is the correct information regarding the FCC ID of the CDMA module. It appears various cover letters and other information may have left off the grantee code, but it is uncertain. Please correct any affected exhibits.
- 3) There have been various concerns regarding the CDMA approval for the module used in this device and that Dennis Ward has recently resolved. However it is noted that the PC still cites that the device may not be co-located. Therefore the PC done may not have clearly identified the co-located environment and therefore the current grant may not yet be covered as used in this device. Please review/explain as necessary.
- 4) It is uncertain if the schematics include the 15.209 RFID transmitter. Please review/explain.
- 5) FYI....Please note that the X-10 portion of the device must be Verified for compliance under 15.31(d) & (h) and 15.201 of the FCC rules, including 3 typical in-situ installations. The scope of this is not covered in the Certification of this application, but the manufacturer is responsible to ensure this testing has been performed. Please confirm this has been performed.
- 6) Table 7.3.3 states MHz. Is this correct?

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.