



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 27, 2006


RE: Visonic Ltd.


FCC ID: GSAPWRMAXPRO

After a review of the submitted information, I have a few comments on the above referenced Application.


- 1) A corrected cover letter was provided regarding the correct information regarding the FCC ID of the CDMA module. However various other exhibits (i.e. operational description) appear to still be incorrect. Please correct.
- 2) Regarding co-location, please provide specific information as to where this information is provided or found (specific training, dates and pages, and/or KDB reference numbers, etc.). Please note that the co-located discussion (in EMC) was poorly worded and created much discussion during training. Further updated slides were released at a later date to help clarify this concern. Note that May training in 2005 clarified that the FCC no longer required EMC co-location testing to be provided unless requested by the FCC. However this did NOT eliminate the fact that it must still be investigated and found to be compliant. Also, the training only clarified that it was no longer necessary to include this in applications to the FCC. Additionally, this fact is ONLY relevant to the EMC co-location and does not address RF co-location issues. RF co-location still followed all specified guidelines. Current information (released January 2006) clearly shows that co-location must be handled in ALL associated applications. Please see below slides and attach exhibits for further information.


-----Original slides -----





-----Updated slides -----





A handwritten signature in black ink, appearing to read "Timothy R. Johnson".

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.