

- 1) The test site used (OAT's/Chamber) must be on record with the FCC via 2.948. From reviewing the FCC site, the OAT's listing could not be found. For example, see the following:

Answer : sorry , I have made some word wrong at test name , it is Shenzhen Electronic Product Quality Testing Center but not the Shenzhen Electronic Products Quality Test Center, I have corrected it ,and you could found it at FCC websit ,the registration number is 261302 .

- 2) Although the test photographs support a fully configured PC per ANSI C63.4, the configuration still does not meet with the positioning requirements. Please refer to previous comment 5). Additionally, please reference section 6 and figure 11a of ANSI C63.4 (i.e.

certain components flush with back and front of the table, when 10 cm spacings between units. It would be expected that the keyboard is flush on the front of the table, the computer, monitor, printer, etc. are flush along the back with 10 cm spacings.

Answer : I have corrected it ,please kindly see the uploaded file which the GW5-SW1000_test report_Rev2 and the GX5-SW1000_set up photos_Rev2.