
Tac/Com 2005 Internal Photographs




Electrical Sub-Assembly Removed From Case




Electrical Sub-Assembly Top View



Bottom View














Modified Maxon Transceiver Showing Modifications





Modified Maxon Transceiver, Top View

Modified Maxon Transceiver, Bottom View




Tac/Com 2005 Internal Photographs (cont.)






Maxon Transceiver RF CCA, Bottom View With Shields




Maxon Transceiver RF CCA, Top View With Shields




Maxon Transceiver RF CCA, Bottom View Without Shields




Tac/Com 2005 Internal Photographs (cont.)




Maxon Transceiver Digital CCA, In Case







Maxon Transceiver RF CCA, Bottom View Without Shield











Transmit Filter CCA, Top View

