


5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

H PATTERN

FRONT VIEW



REAR VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F833104

SIDE VIEW



APPLICANT : PURETEK INDUSTRIAL CO., LTD.

EQUIPMENT : PC CMOS CAMERA

FCC ID : H52PT-6101

ISSUED DATE : APR. 17, 1998

PAGE NUMBER : 15/2000

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F833104


5.5.1 PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

VIDEO MOTION

FRONT VIEW



REAR VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F833104

SIDE VIEW



SPORTON International Inc.
TEL : 886-2-2696-2468
FAX : 886-2-2696-2255


FCC TEST REPORT

REPORT NO. : F833104


6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

H PATTERN

FRONT VIEW



REAR VIEW



6.5.1 PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

VIDEO MOTION

FRONT VIEW



REAR VIEW

