

Federal Communications Commission Authorization and Evaluation Division, 7435 Oakland Mills Road Columbia, MD 21046 USA

Re: FCC ID: H78KPMT2W

Attestation Statement per 90.203(e) and (g)

Programming of transceiver frequencies can only be performed by the manufacturer or authorized service and maintenance personnel. The radio output power is fixed and can't be changed. In addition, there is no RF connector – just integrated internal antenna.

Sincerely,

Liad Kenig

VP, KP Electronic Systems, Ltd.

Cin2 Whig d