FCC ID: H9P2192955

Description of Permissive Change


This report is prepared for FCC class II permissive change. The difference compared with the Report No.: RF960308H04 design is as the following:


- ◆ Add Flip Flop to delay one signal to fix the memory self refresh
- ◆ Shield Modification to improved Harmonic performance in 5GHz

Report No.: RF960308H04D Reference No.: 980827H03

Jedi Permissive Change:

- Add Flip Flop to delay one signal to fix the memory self refresh.





- Shield Modification to improved Harmonic performance in 5GHz.

Before After

