



BABT
Claremont House, 34 Molesey Road
Walton on Thames
Surrey, KT12 4RQ
United Kingdom
Telephone: +44 (0)1932 251251
Fax: +44 (0)1932 251252

Ref: US/000041

Friday, 22 August 2003

To FCC

Direct Dial: +44 (0)1932 251227
E-mail: Hilton.Carr@babt.com
Website: www.babt.com

**Evaluation of Class II Permissive Change to Symbol LA3021 to add host 9010
FCC id: H9PLA3021-100**

I have evaluated the submission and find it compliant.

During the evaluation the following clarifications were made

1: Headset

The MC9000-G Poster indicates the presence of a headset port.

The Client has clarified (see accompanying cover letter) that this model does not currently support such a headset port..

We have advised them that a Class II Permissive Change would be required to add such functionality.

2: Microphone and Speaker

The client has confirmed they operate in loudspeaker mode and are not intended for head operation. Having reviewed the equipment purpose and normal use with a handgrip and are satisfied with this statement.

3: Accessories

The MC9000-G Quick start guide indicates optional snap on accessories.

The Client has clarified these are for hard wire use. The equipment does not transmit while these are in operation. Since they do not draw any power when not in use their effect on the SAR plots was considered to be insignificant.

The Client has confirmed that Symbol do not provide specific belt clips or holsters for use with this product.

Yours sincerely

Allen Ferry
Compliance Manager
For BABT TCB

