



---

**Symbol Technologies, Inc.**

July 10, 2002

Andy Leimer

Re: FCC ID: H9PLA4137

Subject: Response to the request for information

Correspondence Reference number: 23315

731 Confirmation Number: EA665115

Andy Leimer,

In the original application filed on 6/17/02 for a Class II Permissive Change an incorrect FCC ID was referenced, H9PLA4137P with a 731 Confirmation Number EA665115.

Please correct this error to file this Class II Permissive change for FCC ID: H9PLA4137.

Regards,

A handwritten signature in cursive script that reads "Mark S. Luksich".

Mark S. Luksich