



# ***Retlif Testing Laboratories***

795 Marconi Avenue, Ronkonkoma, N.Y. 11779 (631) 737-1500 - FAX (631) 737-1497  ✓  
(Branch Office)

101 New Boston Road, Goffstown, N.H. 03045 (603) 497-4600 - FAX (603) 497-5281

After electronically filing the 731 form for FCC ID H9PPPT4600SOHWEW9, Confirmation No. EA96908. I printed it out and saw that part of the frequency range was placed incorrectly in the "Rated RF power output". The frequency range should be 2414 to 2462 MHz.