

Dali Wireless, Inc. 535 Middlefield Road, Suite 280 Menlo Park, CA 94025 http://www.daliwireless.com

August 15, 2017

TIMCO Engineering, Inc. 849 N.W. State Road 45 P.O. Box 370 Newberry, Florida 32669 USA

## Reference:Attestation Regarding Warning LabelsFCC ID:HCOHD301PSNACI1A

This letter is an attestation that the warning label and class B messages required per 47 C.F.R. § 90.219 will be affixed to the unit, on the outside packaging, in print and on-line versions of the owner's manual and installation instructions, and in on-line point-of-sale marketing materials. A sample of this label is included in the exhibit named "HD301PSNACI1N-LabelSmpl-vX.pdf".

Regards,

Andrew Leung VP, Operations Dali Wireless, Inc.