

Appendix D. SAR Test Setup Photos

Body-worn Exposure Condition (AlphaNumeric)



Front at 15 mm



Back at 15 mm



Front with Holst 1 at 0 mm



Left Side with Holst 2 at 0 mm

Body-worn(Numeric) Exposure Condition



Front at 15 mm



Back at 15 mm

Body-worn Exposure Condition (Large Numeric)



Front at 15 mm



Back at 15 mm

Body-worn Exposure Condition (42keys)



Front at 15 mm



Back at 15 mm

Body-worn Exposure Condition (53keys)



Front at 15 mm



Back at 15 mm

Product Specific Exposure Condition (AlphaNumeric)



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm



Bottom Side at 0 mm

Product Specific Exposure Condition (Numeric)



Front at 0 mm



Right Side at 0 mm



Left Side at 0 mm

Product Specific Exposure Condition (Large Numeric)



Front at 0 mm



Right Side at 0 mm



Left Side at 0 mm

Product Specific Exposure Condition (42keys)



Front at 0 mm



Right Side at 0 mm



Left Side at 0 mm

Product Specific Exposure Condition (53keys)



Front at 0 mm



Right Side at 0 mm



Left Side at 0 mm

PD Exposure Condition (AlphaNumeric)



Front at 2 mm



Back at 2 mm



Left Side at 2 mm



Right Side 2 at 0 mm

PD Exposure Condition (Numeric)



Left Side at 2 mm

PD Exposure Condition (Large Numeric)



Left Side at 2 mm

PD Exposure Condition (42keys)



Left Side at 2 mm

PD Exposure Condition (53keys)



Left Side at 2 mm