



Safety and Productivity Solutions  
9680 Old Bailes Road  
Fort Mill, SC 29707 USA  
[www.honeywell.com](http://www.honeywell.com) [www.honeywellaidc.com](http://www.honeywellaidc.com)

Date: July 14, 2022

Company: **Honeywell International Inc**

To Whom It May Concern,

FCC ID: HD5-CN85L1N

### **AUTHORIZATION LETTER**

Honeywell International Inc hereby authorizes **Amanda Wu / Senior Specialist of Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch (“BV CPS Taoyuan”)**, to act on its behalf in all matters relating to the Federal Communication Commission (“FCC”) application for equipment authorization in connection with the FCC ID listed above, including signing of all documents relating to these matters. Any and all acts carried out by **Amanda Wu / Senior Specialist of BV CPS Taoyuan on Honeywell International Inc’s** behalf, within the scope of the powers granted herein, shall have the same effect as acts of its own.



Safety and Productivity Solutions  
9680 Old Bailes Road  
Fort Mill, SC 29707 USA  
[www.honeywell.com](http://www.honeywell.com) [www.honeywellaidc.com](http://www.honeywellaidc.com)

## Class II Permissive Change

We, Honeywell International Inc, hereby declare that we are only and fully responsible for this CIIPC application of FCC ID: HD5-CN85L1N base on the grant issued on 11/09/2018(DSS/DXX/NII/PCE) and 04/21/2020(DTS).

The application is prepared for FCC class II permissive change for adding the extra SKU which disabled the Ridio 2 (Zigbee+BT) by SW.

The host devices are list as below table for difference of SKU.

Brand	Model	Product Name	USI FG P/N	Description
Honeywell	CN85L1N	Mobile computer	5487-273335-01	CN85G4/UPS/6703SR/CAM/WAN/GMS/FCC
Honeywell	CN85L1N	Mobile computer	5487-275335-01	CN85G4/UPS/6703SR/CAM/WAN/GMS/FCC/No 2nd BT/ No Zigbee

There is an reduced the power level table (Initial table) which to satisfy the FCC rule requirement. The test report will be submitted for evidence. The source code/SW file about this SW will ONLY be held by Honeywell International Inc and it is IMPOSSIBLE to release these source code/SW file to any other third party to affect the RF function, power, or rating of this device.

Except for the changes mentioned above, no other modification is performed.

If you have any questions regarding the authorization, please don't hesitate to contact us.

Sincerely yours,

-----  
Mandana Salahshour  
Mandana.Mobasher@honeywell.com  
Manager - Regulatory Compliance  
Honeywell International Inc  
SPS (Safety and Productivity Solutions)  
Office: +1-803-835-8190