



THE POWER OF **CONNECTED**

**Safety and Productivity Solutions**

9680 Old Bailes Road  
Fort Mill, SC 29707 USA

[www.honeywell.com](http://www.honeywell.com) [sps.honeywell.com](http://sps.honeywell.com)

Date : August 22, 2022

Subject: Statement of Conformity

FCC ID: HD5-TAP1000-02

IC: 1693B-TAP100002

To Whom it may concern,

We, Company Name declare that the device does not support non-US channel, country code selection in all the operational mode(s), like Ad-Hoc...etc. for the following product. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master and the device without support DFS detection capability. This includes restriction on transmissions for beacons and support for ad-hoc peer -to-peer modes.

Sincerely,

Gretchen Bullen

[Gretchen.Bullen@honeywell.com](mailto:Gretchen.Bullen@honeywell.com)

Quality Engineer III – Product Compliance

Honeywell International Inc

SPS (Safety and Productivity Solutions)

Office:+1-412-222-4097