

Date:July 13, 2009

Acer Incorporated 8F, 88, Sec. 1, Hsin Tai Wu Rd., Hsichih Taipei Hsien 221, Taiwan, R.O.C.

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Tel : 886-2-2696-1234 Fax : 886-2-2696-3535 www.acer.com

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: HLZ-AR5B93

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Atheros Communications, Inc. will establish a new FCC ID under Acer Inc. grantee code for purpose of marketing. The original grant to Atheros Communications, Inc. FCC ID: PPD-AR5B93 will remain in effect.

An authorization letter by Atheros Communications, Inc. is attached.

Per 2.933(b)

- 1. The original identification is FCC ID: PPD-AR5B93
- 2. The original grant date is 01/22/2009.
- 3. The equipment is electrically identical. Only the trade name, and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Label format is included in this application.

The following files are electronically submitted as attachments:

Cover Letter External Photos FCC ID label format and location

Sincerely,

Casy Lai

Acer Incorporated (*J* Easy Lai / Manager Phone:886-2-8691-3089 Fax: : 886-2-8691-3120 Email: easy_lai@acer.com.tw Date:February 20, 2009