

## Lucy Tsai

---

**From:** ATL-Joyce [joyce@atl-lab.com.tw]  
**Sent:** Wednesday, March 17, 2010 3:29 AM  
**To:** Lucy Tsai  
**Cc:** miller@atl-lab.com.tw; queenie@atl-lab.com.tw; murphy@atl-lab.com.tw; linda@atl-lab.com.tw  
**Subject:** FW : Acer Incorporated, FCC ID: HLZ-AR5B97, Assessment NO.: AN10T0193, Notice#1  
**Attachments:** Reply File\_100317.rar

Dear Lucy~

Q#1: There has a WWAN ( FCC ID: QISEM770W) installed in this laptop but there are not information address this WWAN module in this application. Where is the antenna located of WWAN? Can the WWAN co-locate with the WLAN module? Please address.

---> It will submitted for Class II permissive change filing by WWAN manufacturer.

**Attach files(Reply File\_100317):**

**1. 1003FR14\_Part 15C WLAN (10-0053)**

Best regards,

廖秋吟 Joyce Liao  
Measurement Center



TEL : +886-3-2710188 ext: 200  
Mobile : +886-935176076  
Address : 桃園縣八德市長安街 140-1 號  
E-mail : [joyce@atl-lab.com.tw](mailto:joyce@atl-lab.com.tw)  
Website : <http://www.atl-lab.com.tw>