

## **Acer Incorporated**

8F, 88, Sec. 1, Hsin Tai Wu Rd., Hsichih Taipei Hsien 221, Taiwan, R.O.C.

> Tel: 886-2-2696-1234 Fax: 886-2-2696-3535 www.acer.com

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID:HLZ-BRCM1050

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Acer Incorporated will establish a new FCC ID under Acer Incorporated., grantee code for purpose of marketing. The original grant to Broadcom Corporation, FCC ID: QDS-BRCM1050 will remain in effect.

An authorization letter by Broadcom Corporation is attached.

Per 2.933(b)

- 1. The original identification is QDS-BRCM1050
- 2. The original grant date is 10/01/2009
- 3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter External Photos FCC ID label format and location

Sincerely,

Name: ( Easy Lai

Title: Manager of Regulatory Center

Date: 02/26/2010