No. 65, Ku Dai Keng St., Hsichih, Taipei 221, R.O. C. Tel: 886-2-2646-2550 FAX: 886-2-26464641 No. 120, Lane 180, San Ho Tsuen, Hsin Ho Rd. Lung-Tan Hsiang, Tao Yuan County 325, Taiwan, R.O.C. Tel: 886-3-407-1718 FAX:886-3-407-1738

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

December 22, 2003

RE: FCC ID: HLZAS1710_ATCB001003

Dear Dennis,

Here are our answer:

1. Please note that there is more than sufficient room on the outside of the laptop to place the 2-condition statement as required by the FCC. When there is sufficient room and when there are no other justifiable reasons, the FCC requires the label to be on the product not in the manual. Please provide a label with the 2-condition statement stated in 15.21.

Ans: I have notified my client to add this warning statment on the label, please see the updated label A. label update.jpg

...... B. label & location update.pdf

2. Please note that the manual states that this device can be used in non-US counties. This indicates that it may operate on non-approved US frequencies. Please verify and confirm that when sold I the US, the user cannot make this device operate on non-US approved channels.

Ans: : I have updated the manual, and also the applicant has provided a declaration letter on frequency range. Please see attachemnt

A. manual part 2 update.pdf

B. frequency DOC letter.pdf

If there is any info needed, please notify us. Thank you for your help.

Sincerely,

Daphne Liu

International Standards Laoboratory