



Date: 28.MAY.2021 15:51:24

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch177




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch177




Date: 28.MAY.2021 16:50:38

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch177




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch177




Date: 28.MAY.2021 17:23:47

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch175




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch177




Date: 31.MAY.2021 08:18:12


BE-NR-LOW, SISO-B, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, SISO-B, 802.11ac80-VHT0, Ch171



BE-NR-LOW, SISO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, SISO-B, 802.11ac160-VHT0, Ch163




Date: 31.MAY.2021 08:02:03

BE-NR-LOW, SISO-B, 802.11ax20-HE0, Ch177




BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch177




Date: 28.MAY.2021 18:09:11

BE-NR-LOW, SISO-B, 802.11ax40-HE0, Ch175




BE-NR-HIGH, SISO-B, 802.11ax40-HE0, Ch175




Date: 31.MAY.2021 08:17:11


BE-NR-LOW, SISO-B, 802.11ax80-HE0, Ch171




BE-NR-HIGH, SISO-B, 802.11ax80-HE0, Ch171



BE-NR-LOW, SISO-B, 802.11ax160-HE0, Ch163




BE-NR-HIGH, SISO-B, 802.11ax160-HE0, Ch163




Date: 27.MAY.2021 10:02:03

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 27.MAY.2021 10:21:50


BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch175




BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175




BE-NR-LOW, MIMO-A, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171



BE-NR-LOW, MIMO-A, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-A, 802.11ac160-VHT0, Ch163




Date: 27 MAY 2021 13:23:02

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch177




BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch177




Date: 27 MAY 2021 13:48:00


BE-NR-LOW, MIMO-A, 802.11ax40-HE0, Ch175




BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch175




BE-NR-LOW, MIMO-A, 802.11ax80-HE0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch171




BE-NR-LOW, MIMO-A, 802.11ax160-HE0, Ch163



BE-NR-HIGH, MIMO-A, 802.11ax160-HE0, Ch163




BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177

Date: 28.MAY.2021 09:03:34




Date: 28 MAY 2021 09:19:24


BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch175




BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




BE-NR-LOW, MIMO-B, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171



BE-NR-LOW, MIMO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-B, 802.11ac160-VHT0, Ch163




Date: 28 MAY 2021 12:04:27

BE-NR-LOW, MIMO-B, 802.11ax20-HE0, Ch177




BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch177




Date: 28 MAY 2021 14:40:35

BE-NR-LOW, MIMO-B, 802.11ax40-HE0, Ch175




BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch175



Date: 28 MAY 2021 14:50:20


BE-NR-LOW, MIMO-B, 802.11ax80-HE0, Ch171




BE-NR-HIGH, MIMO-B, 802.11ax80-HE0, Ch171



Test Report N° 210209-01.TR13



BE-NR-LOW, MIMO-B, 802.11ax160-HE0, Ch163



BE-NR-HIGH, MIMO-B, 802.11ax160-HE0, Ch163