

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

May 2, 2006

RE: Acer, Inc.

FCC ID: HLZBL503G

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The Label exhibit is missing for this device. Please supply a label as appropriate.
- 2.) There are no Schematics supplied for this project. Please supply Schematics especially for the Licensed transmitter section.
- 3.) The Parts List supplied does not include any description or listing of any transmitters other than unlicensed Bluetooth or 802.11a/b/g. Please supply an appropriate Parts List for this device.
- 4.) An RF Exposure estimation (MPE) is required for this device. Please provide. In addition, due consideration must be given if either the WLAN or Bluetooth transmitter is capable of usage simultaneously with the Licensed transmitter for this RF category "Mobile" configuration.
- 5.) It is recommended that an Agent Authorization letter from Acer to Sporton also be provided. Please provide at your first opportunity.
- 6.) FYI: The labeling issue may be critical for this filing. There are three potential transmitters which may or may not have their own full or limited Modular Approvals inside a notebook computer which may or may not need it's own ID. Kindly take particular care of labeling for this computer.

William H. Graff

President and Director of Engineering

William In

mailto: whgraff@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.