



## Change Note

**We, Acer, declare on our sole responsibility that the product difference for HW and SW change.**

Model Name : S100  
Old HW version : V1.0  
Old SW version : Modem : A1-00.18.10  
OS : Acer\_A1\_0.020.01\_EN\_G

New HW version : V1.3  
New SW version : Modem : A1-03.14.03  
OS : a1\_generic1-eng2.1-update1 ÉCLAIR  
eng.alpine,20100415.192237 test-keys

### **The difference between these version is:**

#### **1. H/W**

- A.) For large memory size extension, add one trace between CPU & MCP.
- B.) For EOS rejection enhance, add Zener diode on VBUS trace.
- C.) For Voltage-ripple improve, add bypass cap on CPU power line.
- D.) For ESD enhance on side key, add more ESD protection component on side key trace.
- E.) For EOS rejection enhance on USB connection, add one diode on USB\_ID pin.
- F.) For some Audio distortion coming form Speaker, Amp chip-solution change.

#### **2. SW**

Google has upgrade software version to Android v2.0 from v1.6

### **Point of contact**

Name of Contact    Ben Chen  
Department        TM  
Company Name     Acer Incorporated  
Telephone         02-66063131  
E-mail             Ben\_Chen@acer.com.tw

( Signature )