

⊙  $\pm 0.2$

15 MM

**acer**  
Model No.: W510  
FCC ID: HLZW510  
IC: 1754F-W510  
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZ-T77H389  
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙ +/-0.2

15 MM

**acer**

Model No.: W510P  
FCC ID: HLZW510  
IC: 1754F-W510  
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZ-T77H389  
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙  $\pm 0.2$

15 MM

**acer**

Model No.: W511  
FCC ID: HLZW510  
IC: 1754F-W510  
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZMU733

Contains IC: 1754F-MU733

Contains FCC ID: HLZ-T77H389

Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙ +/-0.2

15 MM

**acer**  
Model No.: W511P  
FCC ID: HLZW510  
IC: 1754F-W510  
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZMU733  
Contains IC: 1754F-MU733  
Contains FCC ID: HLZ-T77H389  
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙ +/-0.2

15 MM

**acer**

Model No.: WT3  
FCC ID: HLZW510  
IC: 1754F-W510  
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZ-T77H389  
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy