




Solder View of Output board



Internal View of UPS




Front View of Power Transformer



Internal View of Output Panel



Component View of Main board



WARNING: FOR CONTINUED PROTECTION AGAINST RISK OF FIRE REPLACE ONLY WITH SAME TYPE AND RATING OF FUSE.

PCBC FR4 UL E168178 © 2003

NEW PRO 700
V1.00

5W6Ω
YAGED

5W6Ω
YAGED

TEST1
1. 2. 3.

Bestar
BS-114S
COIL 12VDC
10 A 120VAC/28VDC

Bestar
BS-114S
COIL 12VDC
10 A 120VAC/28VDC

5W100Ω
YAGED

88S06095-01

Solder View of Main board

