



# Leadtek Research Inc

## RF Declaration Letter

2023-07-14

FEDERAL COMMUNICATIONS COMMISSION  
Authorization and Evaluation Division  
7435 Oakland Mills Road Columbia,  
MD 21046


Dear Sir/Madam,

We, Leadtek Research Inc hereby declare that firmware was set 8Z81 had disable The wireless frequency bands that needs to be shielded support upon system boot-up for all 8Z81 system shipment. Consequently, the user cannot access all the frequency bands mentioned above.

We, Leadtek Research Inc assumes the liability against any problems or damages that might occur in relation to this issue.

Product Name : CaroCare Biomolecular Scanner  
Model Name : 8Z81  
FCC ID: I2I8Z81

Sincerely Yours,

  
Feng Ru Huang/Section Manager  
[ru@leadtek.com.tw](mailto:ru@leadtek.com.tw)

18F, No. 166, Jian-Yi Rd., Chung Ho Dist., New Taipei City Taiwan, R.O.C