

Helen Zhao

Subject: FW: RE: Leadtek Research Inc., FCC ID: I2ILR9559X, Assessment NO.: AN06T5994, Notice#1

Dear Helen:

Please see my reply. Thank you.

Best Regards,
Amanda

-----Original Message-----

Sent: Friday, July 21, 2006 5:34 PM

Subject: Leadtek Research Inc., FCC ID: I2ILR9559X, Assessment NO.:
AN06T5994, Notice#1

Question #1: The block diagram and operational description indicates RF module: Samsung Bluetooth BTPZ50002LA, but schematics show module BTMZ5012. Please clarify which is correct, and make necessary correction to keep consistency.

Ans: The block diagram and operational description are correct. Please see the revised schematics.

Question #2: The user manual shows FCC DoC logo in regulatory statement portion. Please note this device is not a PC peripheral, is not qualified to be authorized through DoC. Please remove FCC DoC logo from the manual.

Ans: We removed FCC DoC logo from the manual, please see the attachment.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

7/28/2006