



July 6, 2017

To may it concern,

This letter is written to request a Class II permissive change for existing FCC ID I6H-318MK1 and IC: 21449-MK1. The component value changes in our keypad transmitter are in 5 components: C6, C7, C8, R8, and R12.

Please see table below.

	Previous value	New Value
C6	15pF	1nF
C7	2.7pF	2.4pF
C8	10pF	12pF
R8	20 0	30
R12	39k0	100k0

These values are all related to the circuit encompassing the SAW transmitter.

Regards,

A handwritten signature in black ink, appearing to read "Rafael Martinez", is positioned below the "Regards," text.

Rafael Martinez
Regulatory Affairs Engineer

