





11AX20MIMO\_Ant1\_6515







Date: 20.JUN.2022 22:41:15

11AX20MIMO\_Ant2\_6515




Date: 20.JUN.2022 22:42:23








11AX20MIMO\_Ant1\_6855



Date: 20.JUN.2022 22:48:25


11AX20MIMO\_Ant2\_6855



Date: 20.JUN.2022 22:49:33




11AX20MIMO\_Ant1\_6875



Date: 20.JUN.2022 22:50:45


11AX20MIMO\_Ant2\_6875



Date: 20.JUN.2022 22:51:56




11AX20MIMO\_Ant1\_6895



Date: 20.JUN.2022 22:54:19


11AX20MIMO\_Ant2\_6895



Date: 20.JUN.2022 22:55:28




11AX20MIMO\_Ant1\_6995



Date: 20.JUN.2022 22:57:08


11AX20MIMO\_Ant2\_6995



Date: 20.JUN.2022 22:58:19




11AX20MIMO\_Ant1\_7095



Date: 20.JUN.2022 22:59:38

11AX20MIMO\_Ant2\_7095




Date: 20.JUN.2022 23:00:45






11AX40MIMO\_Ant1\_5965



Date: 20.JUN.2022 23:02:11


11AX40MIMO\_Ant2\_5965



Date: 20.JUN.2022 23:03:21




11AX40MIMO\_Ant1\_6165



Date: 20.JUN.2022 23:04:36


11AX40MIMO\_Ant2\_6165



Date: 20.JUN.2022 23:05:44




11AX40MIMO\_Ant1\_6405



Date: 20.JUN.2022 23:08:48


11AX40MIMO\_Ant2\_6405



Date: 20.JUN.2022 23:09:57




11AX40MIMO\_Ant1\_6445



Date: 20.JUN.2022 23:11:55


11AX40MIMO\_Ant2\_6445



Date: 20.JUN.2022 23:13:01




11AX40MIMO\_Ant1\_6485



Date: 20.JUN.2022 23:18:12


11AX40MIMO\_Ant2\_6485



Date: 20.JUN.2022 23:16:39




11AX40MIMO\_Ant1\_6525



Date: 20.JUN.2022 23:19:22


11AX40MIMO\_Ant2\_6525



Date: 20.JUN.2022 23:20:32




11AX40MIMO\_Ant1\_6565



Date: 20.JUN.2022 23:21:40


11AX40MIMO\_Ant2\_6565



Date: 20.JUN.2022 23:22:49




11AX40MIMO\_Ant1\_6685



Date: 20.JUN.2022 23:23:59

11AX40MIMO\_Ant2\_6685




Date: 20.JUN.2022 23:25:07






11AX40MIMO\_Ant1\_6845



Date: 20.JUN.2022 23:26:19


11AX40MIMO\_Ant2\_6845



Date: 20.JUN.2022 23:27:26




11AX40MIMO\_Ant1\_6885



Date: 20.JUN.2022 23:28:37


11AX40MIMO\_Ant2\_6885



Date: 20.JUN.2022 23:29:43




11AX40MIMO\_Ant1\_6925



Date: 20.JUN.2022 23:30:56


11AX40MIMO\_Ant2\_6925



Date: 20.JUN.2022 23:32:05




11AX40MIMO\_Ant1\_6965



Date: 20.JUN.2022 23:33:15


11AX40MIMO\_Ant2\_6965




Date: 20.JUN.2022 23:34:22



11AX40MIMO\_Ant1\_7085




11AX40MIMO\_Ant2\_7085






11AX80MIMO\_Ant1\_5985



Date: 20.JUN.2022 23:37:53


11AX80MIMO\_Ant2\_5985



Date: 20.JUN.2022 23:39:02




11AX80MIMO\_Ant1\_6145



Date: 20.JUN.2022 23:40:12


11AX80MIMO\_Ant2\_6145



Date: 20.JUN.2022 23:41:19




11AX80MIMO\_Ant1\_6385



Date: 20.JUN.2022 23:42:29

11AX80MIMO\_Ant2\_6385




Date: 20.JUN.2022 23:43:37






11AX80MIMO\_Ant1\_6465



Date: 20.JUN.2022 23:44:47

11AX80MIMO\_Ant2\_6465



Date: 20.JUN.2022 23:45:55