





11AX20MIMO_Ant1_6855




Date: 21.SEP.2022 19:41:02

11AX20MIMO_Ant2_6855




Date: 21.SEP.2022 19:42:06








11AX20MIMO_Ant1_6895





11AX20MIMO_Ant2_6895


















11AX40MIMO_Ant1_6405




Date: 21.SEP.2022 20:06:26

11AX40MIMO_Ant2_6405




Date: 21.SEP.2022 20:07:30






11AX40MIMO_Ant1_6485




Date: 21.SEP.2022 20:12:15

11AX40MIMO_Ant2_6485




Date: 21.SEP.2022 20:13:19






11AX40MIMO_Ant1_6565





Date: 21.SEP.2022 20:17:19


11AX40MIMO_Ant2_6565





Date: 21.SEP.2022 20:18:21















11AX40MIMO_Ant1_7085



Date: 21.SEP.2022 20:35:14


11AX40MIMO_Ant2_7085



Date: 21.SEP.2022 20:36:14



11AX80MIMO_Ant1_5985



11AX80MIMO_Ant2_5985

