



4\_MOT\_0705\_TAS

Phoenix Test Lab

Mr. Brandhorst

Torsten Lohoff  
09.05.2006  
Phone +49 (0) 2102 749 306  
Fax +49 (0) 2102 749 350

***Re-testing of Motorola H5, FCC ID IHDT6FB1***

Dear Mr. Brandhorst,

we have analyzed the difference between the first hardware version T4 and T6. Full FCC Part 15.247 testing was done on hardware version T4 (see test report 4\_MOT\_0705\_TAS\_FCCc ). After analyzing the changes in hardware version T6 (see also attachment), we came to the conclusion that re-testing of Peak Power Output and Spurious Radiated Emission shall be done (see test report 4\_MOT\_0705\_TAS\_FCCd).

We can also confirm that the changes from FCC rules 2004 to 2005 do not affect the performed test cases.

Best Regards

Torsten Lohoff