




Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS

FCC ID: IHET6DY1

Test Report Exhibit

Spurious Emissions at Antenna Terminal – 45W Channel 1175 – 1.98875 GHz – 8PSK







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1






Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS

FCC ID: IHET6DY1

Test Report Exhibit

Spurious Emissions at Antenna Terminal – 0.45W Channel 25 – 1.93325 GHz – QPSK







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1






Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS

FCC ID: IHET6DY1

Test Report Exhibit

Spurious Emissions at Antenna Terminal – 0.45W Channel 25 – 1.93325 GHz – 16QAM







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1






Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS

FCC ID: IHET6DY1

Test Report Exhibit

Spurious Emissions at Antenna Terminal – 0.45W Channel 25 – 1.93325 GHz – 8PSK







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1







Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1





Global Telecom Solutions Sector

SC4812T-MC 1X/1X-DO @ 1.9 GHz CDMA BTS
Test Report Exhibit

FCC ID: IHET6DY1

