



THE PROFESSIONAL MONITOR COMPANY

TAIWAN VIDEO & MONITOR CORP.

6/F, 141 Jen Ai Rd., Sec. 3, Taipei, Taiwan, R.O.C.
P.O. Box 3338 Taipei Telephone: (02) 771-6361/5
Fax. 886-2-7214798 Telex. 28190 TVMTWN

台灣錄影股份有限公司

台北市仁愛路三段141號六樓 電話: (02) 7716361~5

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Rd.
Columbia, MD. 21046

Date: April 13, 1998

Attention: Authorization and Evaluation Division

Subject: RFI related modifications incorporated
into unit with - FCC ID: IIBUA1

Dear Sirs:

This letter serves as our declaration that all modifications listed below were implemented in the sample submitted for testing. We further declare that the same modifications will be implemented into all production units to enhance compliance of the units to FCC limits.

The modifications include the following:

- 1) Added two ferrite cores on the video cable one outside and one inside the monitor. (see photo 2 & 9)
- 2) Added a metal plate on the rear side of CRT board and it was connected to chassis by four ground wires. (see photo 4 & 5)
- 3) Added four capacitors, one resistor and one bead core for EMI, one jump wires for electrical improvement only and not for EMI. They will be built into component side after circuit relayout. (see photo 10)

If you have any further questions or comments regarding the above, please don't hesitate to contact Mr. Johnson Ho of Spectrum Research and Testing Laboratory at (301) 855-2262.

Sincerely yours,

Blue Lan / Supervisor
Taiwan Video & Monitor Corp.

cc. Mr. Johnson Ho - Spectrum Research and Testing Laboratory
Mr. Harris W. Lai - Advance Data Technology Corporation