



S I N C E

1 8 8 6

August 27, 2002

Mr. Mark Nolting
Mr. James Marley
UL-RTP EMC Test Facility
12 Laboratory Dr.
Research Triangle Park, NC 27709

Dear Sirs:

Hunter Fan Company would like to proceed with a Class II permissive change under the rules 47 CFR Ch. 1, § 2.1043 . The affected unit is a low power remote control transmitter with FCC ID IN2TX13.

The basic operation, functionality, and transmitted power remains unchanged. The unit still uses ASK modulation on a 350 MHz carrier to transmit a digital signal to our ceiling fan remote receivers. The circuit difference is that instead of using a factory-tuned LC oscillator, we are now using a fixed SAW resonator at 350 MHz. The reason for this change is to simplify the production process by removing the tuning step at the factory. Mechanically, the antenna has changed from a copper trace on the circuit board to a small loop antenna. No visible difference is detectable when using the hand-held transmitter.

Thank you for your assistance with this project.

Best regards,

Steve Bias

Engineering Manager

HUNTER FAN COMPANY

2500 FRISCO AVE., MEMPHIS, TENNESSEE 38114 TEL: (901) 743-1360 FAX: (901) 745-9265 CUSTOMER SERVICE FAX: (901) 745-9376