Tuning procedure for GMR404/406.

There are no field adjustable tuning options. The only adjustment is to the 300vdc supply voltage for the magnetron driver circuitry, which is set at the factory. Refer to file 690-A0003-05 for details of the magnetron for the GMR404 and GMR406.

ROGERS LABS, INC. Garmin International, Inc. 4405 W. 259th Terrace MODEL: GMR 40X Louisburg, KS 66053 Test #: 060406

Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 80

IC:1792A-00991 FCCID#: IPH-009910 Page 1 of 1 IPH00991 Tune.doc 5/22/2006