
Internal photographs of transmitter section of equipment under test.

Inside with unit opened.



Transmitter board with shield.




ROGERS LABS, INC. Garmin International, Inc.
4405 West 259<sup>th</sup> Terrace MODEL: 011-01326-0x SN: Eng 1
Louisburg, KS 66053 Test #:060208 FCC ID#: IPH-01017 IC:1792A-01017 Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.249, RSS-210 Page 1 of 2

IPH 01017 Tx Int Phot.Doc 3/29/2006

Transmitter printed circuit board solder side.



Transmitter section without shield.



ROGERS LABS, INC. Garmin International, Inc.
4405 West 259<sup>th</sup> Terrace MODEL: 011-01326-0x SN: Eng 1
Louisburg, KS 66053 Test #:060208 FCC ID#: IPH-01017 IC:1792A-01017 Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.249, RSS-210 Page 2 of 2