

Each units TX functionality is tested and judged with a pass/fail criteria during production.
Units meeting the criteria continue through production and others are returned for diagnostics.
The design offers no provision for tune up procedure.

Rogers Labs, Inc.

4405 West 259th Terrace

Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.

Model: 01101697

Test #: 071116 SN: B8

Test to: FCC Parts 2, 15.239, RSS-210

File TunPro 01249

FCC ID#: IPH-01249

IC: 1792A-01249

Page 1 of 1

Date: 12/20/2007