Tune-up Procedure for 011-02043-xx

Crystal Y502 serves as a reference to I502 transceiver. Y502 does not have any adjustment.

Transceiver functional performance is measured both at board level test and final test during production.

Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053

Revision 1

Garmin International, Inc.

TunPro IPH 01475

Model: Forerunner 310XT GPN: 011-02043-00 Test #: 090306 SN: DC46ED0200070 Phone/Fax: (913) 837-3214 Test to: CFR47 Parts 2 and 15.249, RSS-210

Page 1 of 1

Date: April 2, 2009

FCC ID#: IPH-01475

IC: 1792A-01475