



Garmin International, Inc.
1200 East 151st Street
Olathe, Kansas 66062
P: 913-397-8200 F: 913-397-8282

May 14, 2009

Dear Sir/Ma'am,

The FCC identifier was located inside the battery compartment on this device because of limited areas. The device is small, wrist-mounted navigator device with many curved surfaces. The top side is taken up by a large lens, Garmin logo and the name of each button function, and the bottom side consists of a removable battery compartment cover and many uneven surfaces.

The FCC identifier will be readily viewable as it will be visible each time the batteries are replaced in the device. Since this device will be sold without batteries installed, the user will have to install batteries prior to using, thus they will see the FCC identifier prior to using the device for the first time.

Sincerely,

A handwritten signature in black ink, appearing to read "Paul Phrommany".

Paul Phrommany
Compliance Engineer
Email: Paul.phrommany@garmin.com
URL: www.garmin.com