Transmitter Tune-Up Procedure

No transmitter tune-up is required for either the ANT or WUSB transceiver. Power and deviation are calibrated in the Cypress and Nordic factories at the time of IC assembly. Frequency reference is determined by crystal oscillator.

Revision 1

Garmin International, Inc. Model: Astro 320 Test #:110420

Test to: FCC Parts 2 and 15.249 File: TunPro DXT IPH01848

FCC ID: IPH-01848

SN: ENG1

GPN: 011-02606-0x Date: June 2, 2011

Page 1 of 1