
Test setup photographs



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup

SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 1 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup

SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 2 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup


SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 3 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup


SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 4 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup

SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 5 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup

SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 6 of 7



Garmin International, Inc.

Test: 181110 Test to: CFR47 15.249 87 RSS-210 Date: February 13, 2019 File: 0225612 TSup

SN's: 51W000108, 51Y000104 FCC ID: IPH-0225612 IC:1792A-0225612 Page 7 of 7